



December 2010

Photo 1. Shows typical flooded golf course scene from 2010 rain event demonstrating the potential for this to be a functioning wetland.





Photo 2. Shows flooded golf course scene from 2005 rain event demonstrating the potential for this to be a functioning wetland and showing an arizona crossing between project site and Devereux slough that has been replaced by a bridge which will allow for tidal connection, and continued road use once site is restored.