

Exhibit B: Site Images



Overtopping of HWY 101



Flooding of HWY 101



Wave-induced Damage to HWY 101



Wave Attack on Revetment Fronting Restaurant Row

Figure 1: Coastal Flooding