


Item 6a – Exhibit 2: Site Photos

Entrance to the alley across the street from Quincy Jones Elementary School. Illegal dumping present.



Dry weather runoff ponding in the alley closest to the market.



Community members photograph what they don't like about the Quincy Jones alley network.



Community members photograph what they don't like about the Quincy Jones alley network.

